






























Name	Breite	Tiefe	Höhe	Sichtbarkeit
 Toilette	29	63	62	x
 Waschbecken	56	47	97	x
 Dusche	79	79	211	x
 Küchenschrank	60	64	85	x
 Gefrierkombination	60	66	185	x
 Kühlschrank	60	66	85	x
 Dunstabzugshaube	60	52,6	94	x
 Ofen	60	62	85	x
 Küchenschrank	60	64	85	x
 Küchenschrank	60	64	85	x
 Küchenschrank	60	64	85	x
 Küchenschrank	60	64	85	x
 Fenster	91	10,2	174	x
 Fenster	91	10,2	174	x
 Fenster	91	10,2	174	x
 Fenster	91	10,2	174	x
 Fenster	91	10,2	174	x
 Fenster	91	10,2	174	x
 Tür	91,5	14,5	208,5	x
 Tür	91,5	14,5	208,5	x
 Tür	91,5	14,5	208,5	x
 Tür	91,5	14,5	208,5	x
 Tür	91,5	14,5	208,5	x
 Tür	91,5	14,5	208,5	x
 Tür	91,5	14,5	208,5	x
 Tür	91,5	14,5	208,5	x
 Tür	91,5	14,5	208,5	x
 Tür	91,5	14,5	208,5	x
 Küchenschrank	60	64	85	x

